



Aerial shot of field during flooding



Water level reached just below concession ceiling



Pictures of the inside of the concession



Damage to infield and first base fence line