

## Aluminum Bat Care

Keep bats in good condition by following the care guidelines below. These guidelines are for aluminum alloy bats CU31 and higher:

- Do not store aluminum bats in an extremely hot area, such as the trunk of a car, as this will weaken the aluminum.
- Aluminum bats are sensitive to cold temperatures (below 60 degrees). Balls become denser in cooler weather and result in a harder impact with the bat.
- To help prevent dents, rotate the bat with each trip to the plate.
- Do not use bats in commercial batting cages. The balls are too dense.